Building Safety

Annexure D

BUILDING SAFETY CERTIFICATE

No 138 Dated 10-11-2025

It is certified that the existing building ...आदर्श विद्या मन्दिर..... (name of the building or premises) at ....आदर्श नगर जयपुर..... ..... (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block
No. of Floors) in the Block	G.F + 2					

The building is owned/occupied by. आदर्श विद्या मन्दिर (the institution) have complied with the Building safety requirements in accordance with National Building code Rules and verified by the officers concerned of .P.W.D. JAIPUR (Name Department/ Govt.) on..10-11-2025.....(date of inspection) in the presence of SANJEEV BHARGAVA SEC. PRABANDH SAMITI A.V.M (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupation running school with effect from 10-11-2025 for a period of .....03..... .... years in accordance with rule and subject to compliance of the specific conditions as appended.

1
2.
3
4

Issued on 10-11-2025 ..... at ...3:40 P.M. ..... by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : Dec/2025
Name . सहायक अभियन्ता
Designation : भा.शि. उपखण्ड शिक्षा समिति जयपुर
Name & Address of Department/ Office: _____

65 |

Self attested

PRINCIPAL
Adarsh Vidhya Mandir (CBSE)
Near Dashehara Ground
Adarsh Nagar, JAIPUR-302004

Scanned with OKEN Scanner

Scanned with OKEN Scanner